

| Northampton District Scouts - Asbestos Register | | | | | | | | | Survey Type: - Management | | | | | | | | |
|--|--------|-------------|--|--------------------------|-------------------------|---------------------------------------|-----------------|---------------|--|--|--------------------------|--------------------------|----------------|-----------------------|---|--|--|
| Site: - Overstone Scout Campsite & Activity Centre | | | | | | | | | Date of Survey: - December 2021 | | | | | | | | |
| Business Unit | Floor | Room | Position | Description | Fibre Type | Comment | Assessment Date | Product Type | Extent m ² (m ² area) (l = length) | Condition | Material Risk Assessment | Priority Risk Assessment | Overall I Risk | Overall Risk Category | Recommendation | | |
| Pack Holiday Centre | Ground | 00006 | Above Ceiling tiles and External | Disused Flue | Chrysotile | Good condition - above ceiling tiles | 4 Dec 2021 | Cement | 2(l) & 3(l) | Good | 3 | 1 | 4 | Minor | Leave in situ and inspected routinely | | |
| Pack Holiday Centre | First | 01002 | Water Tank | Gasket | Chrysotile | Within pipe work | 4 Dec 2021 | Gasket | <1 | Good primarily encased | 2 | 1 | 3 | Minor | Leave in situ and inspected routinely | | |
| Pack Holiday Centre | First | External | Undercloak to Roof | Cement Lining | Chrysotile | Good condition not readily accessible | 4 Dec 2021 | Cement | 40(l) | Mainly in good condition | 2 | 1 | 3 | Low | Leave in situ and inspected routinely | | |
| The Royal Building | Ground | 00001-00005 | Wall | Lining | Chrysotile & Amosite | Lining Board | 4 Dec 2021 | Cement Board | 60 | Good Sealed | 3 | 5 | 8 | Low | Leave in situ and inspected routinely | | |
| The Royal Building | Ground | 00001-00005 | Ceiling | Lining | Amosite and Crocidolite | Lining Board | 4 Dec 2021 | Cement Board | 36 | Good Sealed - Slight Bowing | 4 | 4 | 8 | Low | Leave in situ and inspected routinely | | |
| The Royal Building | Ground | External | Wall | Lining | Chrysotile | Lining Board | 4 Dec 2021 | Cement Board | 36 | Weathered some presumed behind timber cladding | 2 | 1 | 3 | Minor | Leave in situ and inspected routinely | | |
| Blackthorn Hub+A1 | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | Textured Coated Ceiling | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| Will Smith Building | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | Sink Pad | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| Tractor Shed / Workshop | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| Maintenance Portacabin - Green | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| Woodland Bottom Shelter | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| BBQ Shelter | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | - | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| Top Field Shelter | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | - | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| 2000s Toilet Block | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | - | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| Main Fire Shelter | | | No ACMs Detected within the Remit of an Asbestos Management Survey | | | - | 4 Dec 2021 | | | | 0 | 0 | 0 | | Undertake R&D should any Refurbishment be planned | | |
| Blackthorn Woods Toilets | Ground | Girls | Floor | Thermoplastic Floor Tile | Chrysotile | Grey Floor Tiles | 4 Dec 2021 | Thermoplastic | <1 | Good | 6 | 4 | 10 | Low | Door Lining - Licensed if Work required | | |
| Blackthorn Woods Toilets | First | External | Roof | Corrugated Cement | Chrysotile | Good condition not readily accessible | 4 Dec 2021 | Cement | 40(l) | Weathered | 2 | 1 | 3 | Low | Leave in situ and inspected routinely | | |